# Oil Field Environmental Incident Summary

**Responsible Party:** WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: ROVELSTAD 21-13H

Field Name: TIMBER CREEK Well File #: 20014

Date Incident:1/12/2015Time Incident:08:00Facility ID Number:County:MCKENZIETwp:150Rng:100Sec:13Qtr:

Location Description: The majority of the spill remained on site. A small mist left the site to the north

about 15 feet and to the northeast of the site about 15 feet.

Submitted By: Daniel Ryan Received By:

Contact Person: Daniel Ryan

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
15 Gallons 15 gallons

Brine Other

Oil

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/29/2015 Clean Up Concluded: 1/28/2015

Risk Evaluation:

None.

Areal Extent:

15 feet off of location to the north and 15 feet off location to the northeast.

## Potential Environmental Impacts:

None noted.

## Action Taken or Planned:

Impacted snow will be scooped up using a bobcat, then transported to an approved disposal site.

Wastes Disposal Location: An approved disposal site.

Agencies Involved:

### **Updates**

Date: 1/16/2015 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Spray off location. Followup is necessary.

Date: 1/29/2015 Status: Inspection Author: Espe, Brady

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

I arrived at the site at 10:58 a.m. The weather was clear, 25 °F with wind from the northwest at 5-10 mph. The snow has melted in the area, but the ground was frozen. The area north of the well pad is the road ditch, and there is a stubble field to the east. I could see wheel tracks in ditch and on northeast corner of well pad. I could not see any oil staining on stubble or dried-up vegetation. More followup required. 47.819250, - 103.426267

Date: 2/3/2015 Status: Inspection Author: Suess, Bill

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Impacted snow has been removed, and no soil impacts were visible. No further action is warranted.

Date: 5/14/2015 Status: Inspection Author: Espe, Brady

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

I arrived at the site at 13:45 p.m. The weather was cloudy, 48°F, with the wind from the northeast 5-10 mph. The area in the ditch was scraped, and vegetation is coming back. Cropland has been seeded, and the crop is coming back. No further followup needed.